

**Environmental Survey at ACC Rio Grande Campus
December 13, 2001**

Sample	Room	Location	Reading	Time	Temp	RH, %	Coll	Rec
001	221.0	2' height by main door	0.000	1332	70.2	42.4	MM	QS
002		Floor level, SW corner	0.000	1334	70.3	39.8		
003		Breathing zone, center	0.000	1336				
004		Floor level, SE corner	0.000	1337				
005		Breathing zone, SE wall	0.000	1337				
006		2' height, NE side	0.000	1338				
007		Above ceiling, NE side	0.000	1340				
008		Above ceiling, SE corner	0.000	1341				
009		Above ceiling, SE corner	0.000	1343				
010		Air supply vent, SE corner	0.000	1344				
011		Above ceiling, close to surface	0.000	1346	73.8	38.9		
012	221.1	Office, above ceiling, near P-trap	0.000	1347				
013		Office, air supply vent	0.000	1348				
014		Office, breathing zone by desk	0.000	1348				
015	316.0	2' height, NE corner	0.000	1356				
016		2' height, lab table, N end	0.000	1357	75.8	35.4		
017		Floor level, lab table, N end	0.000	1358				
018		Fume hood, W side	0.000	1358				
019		Sink drain, instructor's lab bench, S side	0.000	1359				
020		Floor level, instructor's lab bench, S side	0.000	1359				
021		Floor level, fume hood	0.000	1400				
022		Breathing zone, back fume hood	0.000	1400				
023		First lab bench, S side	0.000	1401				
024		Between benches, second lab bench, S side	0.000	1401				
025		Floor level, wall between 1st & 2nd benches	0.000	1403				
026		Floor level, under ice machine, SW corner	0.000	1404				
027	315.0	Supply room, floor	0.000	1404				
028		Supply room, breathing zone	0.000	1406				
029		Lab table, N end, inside cabinet	0.000	1407				
030	Hall	Floor penetration outside room 316.0	0.000	1413	77.3	36.0		
031	318.0	SW corner	0.000	1415				
032		Table top, S wall	0.000	1417				
033		Floor level, table by S wall	0.000	1417	76.3	25.5		
034		1' height, flammable/gray cabinet	0.000	1418				
035		Indentation, E wall	0.000	1419				
036		Indentation, E wall, repeat	0.000	1419				
037		Second lab table	0.000	1420				
038		Second lab table	0.000	1420				
039		Floor under refrigerator	0.000	1421				
040		Floor level, first lab table sink	0.000	1421				
041		NE corner	0.000	1422				
042		Sink drain, first lab table	0.000	1424				
043	318.1	Shelf, oxy #1	0.000	1427				
044		SW wall	0.000	1428				
045		SE corner	0.000	1428				
046		SW corner	0.000	1428				
047		Opened bottle HgCl ₂	0.024					
048	312.1	Storage room, microbiology	0.000		80.6	32.2		
049		W wall	0.000	1435				
050		E wall	0.000	1436				